


Features

- KOHLER cast iron
- Acid-resistant enamel finish
- Double (equal) compartment
- 1-hole (-1), 3-hole (-3), 4-hole (-4), or 5-hole (-5U)
- 33" (838 mm) x 22" (559 mm)

Codes/Standards Applicable

Specified model meets or exceeds the following:

• ASME A112.19.1/CSA B45.2



BROOKFIELD

KITCHEN SINK

K-5846

Colors/Finishes

- 0: White
- Other: Refer to Price Book for additional colors/finishes

Accessories:

- CP: Polished Chrome
- ST: Stainless Steel
- Other: Refer to Price Book for additional colors/finishes

Model	Description	Description		Colors/Finishes	
K-5846-1	Top-mount kitchen sink with one hole (sho	wn)	0 🗆	□ Other	
K-5846-3	Top-mount kitchen sink with three holes	Top-mount kitchen sink with three holes		Other	
K-5846-4	Top-mount kitchen sink with four holes		0	□ Other	
K-5846-5U	Under-mount kitchen sink with five holes		0	Other	
Recomment K-9000	nded Accessories			CP	
K-9000				CP	
K-9000	P-Trap	□ ST			
K-9000 Optional A	P-Trap ccessories	□ ST □ ST		CP Other	

Specified Model

Product Specification

The cast iron sink shall be 33" (838 mm) in length, and 22" (559 mm) in width. Sink shall have an acid-resistant enamel finish. Sink shall feature double (equal) compartment. Sink shall be available with one, three or four holes for top-mount installations or five holes for under-mount installations. Sink shall be Kohler Model K-5846-_____.

BROOKFIELD


Technical Information

Fixture*:					
Basin area	14-3/16" (360 mm) x 16-1/16"				
	(408 mm)				
Water depth	9″ (229 mm)				
Drain holes	Ø 3-7/8" (98 mm)				
Faucet holes	Top-mount: Ø 1-3/8" (35 mm)				
	Under-mount: Ø 2-3/8	3″ (60 mm)			
* Approximate measurements for comparison only.					
Included components:					
Cut-out template	1174556-7				
Under-mount sink kit 2	1054375				

Installation Notes

Install this product according to the installation guide.

NOTICE: Countertop manufacturer or cutter must use the cut-out template provided with the product, or a current one provided by Kohler Co. (call 1-800-4-KOHLER). Kohler Co. is not responsible for cutout errors when the incorrect cut-out template is used.



BROOKFIELDTM KITCHEN SINK Page 2 of 2 1179926-4-A